



Los Angeles Fire Department - Official Inspection Report
COMPLAINT FOLLOW-UP
 200 N. Main Street
 Los Angeles, CA 90012
 (213) 978-3680
www.lafd.org



INSPECTOR NAME: ALVIN DONG	PHONE: 2132383515	DISTRICT:	FIRE STATION:	APN:	NOTICE#: DA98ZFSVF	INSPECTION DATE: 12/15/2021
--------------------------------------	-----------------------------	------------------	----------------------	-------------	------------------------------	---------------------------------------

	PAT VIGEANT Pacific Coast Energy Company LP (West Pico) 9151 W PICO BLVD LOS ANGELES, CA 90035 (310) 271-7560	CERS ID: 10248883 FACILITY ID: FA0023350 RECORD ID: COAAXXQRI
--	--	---

NVO = No Violation OUT = Out of Compliance UD = Undetermined NA = Not Applicable COS = Corrected Onsite RPT= Repeat Violation

Actual or threatened release reported to the unified program agency and Cal OES

NVO OUT UD NA COS RPT

CLASS II
COMPLY BY: 1/14/2022

Violation Description:

Failure to report a release or threatened release of a hazardous material to the unified program agency and Cal OES. 19 CCR 4 2631; HSC 6.95 25510(a)

Violation Comments:

Please report your release from Saturday evening to the LAFD CUPA,
<https://docs.google.com/forms/d/e/1FAIpQLSdlFk4XINWr-c-se1u2MMOHh13sdCCyQVMJfcigYmAXFF9sPw/viewform>

Submission made during the inspection.

Abate violation.

Overall Inspection Comments

Met Pat Vigeant, Production Foreman, who gave consent to inspect and take pictures.

Mr. Vigeant detailed the cause of the release and the events to mitigate the effects of the release of crude oil from the evening of Saturday, 12.11.2021.

Underground piping had been blinded years ago. The blind developed a pinhole leak and crude oil was detected oozing from the wall adjacent the alley across the street in at 9101 W Pico, approximately 10-15 feet from Oakhurst. Operations were halted to stop the release and determine the source. Notification was made to CalOES that evening. A contractor, Patriot Environmental, was called out to clean up the spill. Approximately 15 gallons of material were estimated to have been recovered. Per Mr. Vigeant, the material stayed in the alley did not reach the street between Oakhurst and Doheny. No evidence of staining was observed on either Oakhurst nor Doheny.

The contractor cleaned up the spill by Sunday, 12.12.2021, and the underground piping was purged and cleaned. Additional cleaning was performed Monday evening 12.13.2021 at the request of HHMD.

The underground piping has been disconnected from the existing active piping. The abandoned piping will be filled with slurry.

Notification of the spill has been submitted to the CUPA this date and the violation has been abated.

copy to:

Rick Clark <rick.clark@pceclp.com>
 Pat Vigeant <pvigeant@pcedp.com>



Los Angeles Fire Department - Official Inspection Report
COMPLAINT FOLLOW-UP
200 N. Main Street
Los Angeles, CA 90012
(213) 978-3680
www.lafd.org



BUSINESS NAME:

FACILITY ID:
N/A

NOTICE#:
DA98ZFSVF

INSPECTION DATE:
12/15/2021

This report shall serve as a "NOTICE TO COMPLY" for Minor Violations, and a "NOTICE OF VIOLATION" for Major violations. Formal enforcement and/or penalty assessment may be initiated for any violations noted, and for those not corrected in a timely manner. You are, hereby, ordered by the Fire Chief to correct the above noted violations **WITHIN 30 DAYS, OR FORTHWITH IF INDICATED IN THE CORRECTION SUMMARIES PROVIDED.**

All businesses within the City of Los Angeles that store or handle hazardous materials above reportable quantities are required to submit a Hazardous Materials Business Plan (HMBP) annually to CERS cers.calepa.ca.gov. Any business that submits after the March 1st deadline may be subject to a late submittal fee of \$500.00, pursuant to the Los Angeles Municipal Code (L.A.M.C.), and/or enforcement action, pursuant to California Health and Safety Code (H&SC), Section 25508(a)(3).

Violators can be liable for civil penalties up to \$5,000 per day, for each violation. HSC 25299, HSC 25515, HSC 25270.12

Customer Feedback Survey

Please take a moment to participate in our Los Angeles Fire Department CUPA customer feedback survey by utilizing the link below:
<https://www.surveymonkey.com/r/CUPAFEEDBACK>

LAFD CUPA information

For further information or questions please visit the following link:
<https://www.lafd.org/fire-prevention/cupa>

Signatures

Pat Vigeant

Production Foreman

